

TOP SECRET**PRIORITY**

OUT56175

1**T O P S E C R E T 141818**

1965 JUL 14 18 29Z

PRIORITY [] 4954

25X1

IDEALIST**ATTN:** []

25X1

SUBJECT: EVALUATION OF MISSION C365C

1. CAMERA C119 WAS USED IN MISSION C365C FLOWN ON 3 JULY 65.
PROCESSING WAS ACCOMPLISHED IN THE FIELD.

14 JUL 1965

2. ORIGINAL NEGATIVE:

A. EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: HEAT SPLICES ARE PRESENT BETWEEN FRAMES 93/94, 226/227, 619/620, 624/625, 718/719, 851/852, 873/874, 984/985 AND 1117/1118. WAVERING PLUS DENSITY STREAKS, NEAR THE INBOARD EDGE, ARE PRESENT INTERMITTENTLY ON FRAMES 626 TO 652, 671 TO 713, 4 AND 1075 TO 1107. EMULSION LIFTS ARE NOTED IN FRAME 624. TWO SMALL STAINS OF AN UNKNOWN SUBSTANCE OCCUR IN FRAME 208.

C. 9L SIDE: THERE IS AN AREA OF SLIGHT FOG EXTENDING FROM THE INBOARD EDGE OF THE FILM IN FRAME 17. HEAT SPLICES OCCUR BETWEEN FRAMES 93/94, 226/227, 229/230, 359/360, 492/493, 499/500, 615/616, 624/625, 718/719, 851/852, 871/872, 984/985 AND 1117/1118. A BAND OF FOG ROUGHLY 1.9" WIDE APPEARS ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. FAINT IMAGES OF THE ADJACENT POSITION INDICATOR IS IMAGED. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 347.

COPIES RECEIVED.		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	STC BR	
	ECSS	
	CSS	
	WD	
	PD	
	PCD	
	PC-ICB	
3,4	HD	
	PID	
	PAG	
	DIAAX-4	
	SPAD	
	NSA-IO	
	DIA-AP	

1**TOP SECRET**

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1

-2-

D. BOTH SIDES: INTERMITTENT EDGE STATIC IS PRESENT ALONG BOTH FILM'S EDGES. PRESSURE ROLLER STATIC (CHATTER) OCCURS NEAR THE INBOARD EDGE THROUGHOUT THE FILM. FRAMES ARE TITLED CONSECUTIVELY FROM 0000 THROUGH 1189.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 30 PERCENT OF THE MISSION.

T O P S E C R E T

-END OF MESSAGE-

1